

The canister sample due for collection on September 14, 2011 did not run as scheduled. The computer that runs the program controlling the canister sampler performed an auto-update on the computer clock. The default to Pacific time zone disrupted the program timer and caused the sample to not be collected. The configuration of the computer has been amended so it will not seek to auto-update in the future.