

The results set forth herein are provided by SGS North America Inc.

e-Hardcopy 2.0
Automated Report

Technical Report for

Providence Engineering

Valero-CAMS, Baton Rouge, LA

712-001

SGS Job Number: JD37553

Sampling Date: 12/25/21

Report to:

Providence Engineering

kevincalhoun@providenceeng.com

ATTN: Kevin Calhoun

Total number of pages in report: 10



Test results contained within this data package meet the requirements of the National Environmental Laboratory Accreditation Program and/or state specific certification programs as applicable.

A handwritten signature in black ink, appearing to read "Mike Earp".

Mike Earp
General Manager

Client Service contact: Jadon Schiller 732-329-0200

Certifications: NJ(12129), NY(10983), CA, CT, FL, IL, IN, KS, KY, LA, MA, MD, ME, MN, NC, OH VAP (CL0056), AK (UST-103), AZ (AZ0786), PA, RI, SC, TX, UT, VA, WV, DoD ELAP (ANAB L2248)

This report shall not be reproduced, except in its entirety, without the written approval of SGS.
Test results relate only to samples analyzed.

Table of Contents

-1-

| | |
|--|-----------|
| Section 1: Sample Summary | 3 |
| Section 2: Sample Results | 4 |
| 2.1: JD37553-1: CAMS 630 | 5 |
| Section 3: Misc. Forms | 7 |
| 3.1: Chain of Custody | 8 |
| 3.2: Summa Canister and Flow Controller Log | 10 |

1

2

3



Sample Summary

Providence Engineering

Job No: JD37553

Valero-CAMS, Baton Rouge, LA
Project No: 712-001

| Sample Number | Collected Date | Time By | Received | Matrix Code Type | Client Sample ID |
|---------------|----------------|---------|----------|------------------|------------------|
|---------------|----------------|---------|----------|------------------|------------------|

This report contains results reported as ND = Not detected. The following applies:
Organics ND = Not detected above the MDL

| | | | | | | | |
|-----------|----------|-------|-----|----------|-----|-------------------|----------|
| JD37553-1 | 12/25/21 | 09:45 | CIG | 12/31/21 | AIR | Ambient Air Comp. | CAMS 630 |
|-----------|----------|-------|-----|----------|-----|-------------------|----------|

Sample Results

Report of Analysis

Report of Analysis

| | | | |
|-------------------|---|-----------------|----------|
| Client Sample ID: | CAMS 630 | Date Sampled: | 12/25/21 |
| Lab Sample ID: | JD37553-1 | Date Received: | 12/31/21 |
| Matrix: | AIR - Ambient Air Comp. Summa ID: A1174 | Percent Solids: | n/a |
| Method: | TO-15 | | |
| Project: | Valero-CAMS, Baton Rouge, LA | | |

| Run # | File ID | DF | Analyzed | By | Prep Date | Prep Batch | Analytical Batch |
|--------|-----------|----|----------------|-----|-----------|------------|------------------|
| Run #1 | 5W47252.D | 1 | 01/05/22 14:54 | DFT | n/a | n/a | V5W1953 |
| Run #2 | | | | | | | |

| Run # | Initial Volume |
|--------|----------------|
| Run #1 | 400 ml |
| Run #2 | |

VOA TO15 List

| CAS No. | MW | Compound | Result | RL | MDL | Units | Q | Result | RL | MDL | Units |
|------------|-------|----------------------------|--------|------|-------|-------|---|--------|------|------|-------|
| 67-64-1 | 58.08 | Acetone (2-Propanone) | 5.0 | 0.20 | 0.15 | ppbv | | 12 | 0.48 | 0.36 | ug/m3 |
| 106-99-0 | 54.09 | 1,3-Butadiene | ND | 0.20 | 0.084 | ppbv | | ND | 0.44 | 0.19 | ug/m3 |
| 71-43-2 | 78.11 | Benzene | 0.49 | 0.20 | 0.062 | ppbv | | 1.6 | 0.64 | 0.20 | ug/m3 |
| 75-27-4 | 163.8 | Bromodichloromethane | ND | 0.20 | 0.030 | ppbv | | ND | 1.3 | 0.20 | ug/m3 |
| 75-25-2 | 252.8 | Bromoform | ND | 0.20 | 0.071 | ppbv | | ND | 2.1 | 0.73 | ug/m3 |
| 74-83-9 | 94.94 | Bromomethane | ND | 0.20 | 0.069 | ppbv | | ND | 0.78 | 0.27 | ug/m3 |
| 593-60-2 | 106.9 | Bromoethene | ND | 0.20 | 0.061 | ppbv | | ND | 0.87 | 0.27 | ug/m3 |
| 100-44-7 | 126 | Benzyl Chloride | ND | 0.20 | 0.037 | ppbv | | ND | 1.0 | 0.19 | ug/m3 |
| 75-15-0 | 76.14 | Carbon disulfide | ND | 0.20 | 0.045 | ppbv | | ND | 0.62 | 0.14 | ug/m3 |
| 108-90-7 | 112.6 | Chlorobenzene | ND | 0.20 | 0.074 | ppbv | | ND | 0.92 | 0.34 | ug/m3 |
| 75-00-3 | 64.52 | Chloroethane | ND | 0.20 | 0.068 | ppbv | | ND | 0.53 | 0.18 | ug/m3 |
| 67-66-3 | 119.4 | Chloroform | ND | 0.20 | 0.037 | ppbv | | ND | 0.98 | 0.18 | ug/m3 |
| 74-87-3 | 50.49 | Chloromethane | 0.41 | 0.20 | 0.090 | ppbv | | 0.85 | 0.41 | 0.19 | ug/m3 |
| 107-05-1 | 76.53 | 3-Chloropropene | ND | 0.20 | 0.083 | ppbv | | ND | 0.63 | 0.26 | ug/m3 |
| 95-49-8 | 126.6 | 2-Chlorotoluene | ND | 0.20 | 0.072 | ppbv | | ND | 1.0 | 0.37 | ug/m3 |
| 56-23-5 | 153.8 | Carbon tetrachloride | 0.096 | 0.20 | 0.040 | ppbv | J | 0.60 | 1.3 | 0.25 | ug/m3 |
| 110-82-7 | 84.16 | Cyclohexane | ND | 0.20 | 0.11 | ppbv | | ND | 0.69 | 0.38 | ug/m3 |
| 75-34-3 | 98.96 | 1,1-Dichloroethane | ND | 0.20 | 0.057 | ppbv | | ND | 0.81 | 0.23 | ug/m3 |
| 75-35-4 | 96.94 | 1,1-Dichloroethylene | ND | 0.20 | 0.059 | ppbv | | ND | 0.79 | 0.23 | ug/m3 |
| 106-93-4 | 187.9 | 1,2-Dibromoethane (EDB) | ND | 0.20 | 0.097 | ppbv | | ND | 1.5 | 0.75 | ug/m3 |
| 107-06-2 | 98.96 | 1,2-Dichloroethane | ND | 0.20 | 0.070 | ppbv | | ND | 0.81 | 0.28 | ug/m3 |
| 78-87-5 | 113 | 1,2-Dichloropropane | ND | 0.20 | 0.062 | ppbv | | ND | 0.92 | 0.29 | ug/m3 |
| 123-91-1 | 88.12 | 1,4-Dioxane | ND | 0.20 | 0.12 | ppbv | | ND | 0.72 | 0.43 | ug/m3 |
| 75-71-8 | 120.9 | Dichlorodifluoromethane | 0.40 | 0.20 | 0.032 | ppbv | | 2.0 | 0.99 | 0.16 | ug/m3 |
| 124-48-1 | 208.3 | Dibromochloromethane | ND | 0.20 | 0.052 | ppbv | | ND | 1.7 | 0.44 | ug/m3 |
| 156-60-5 | 96.94 | trans-1,2-Dichloroethylene | ND | 0.20 | 0.069 | ppbv | | ND | 0.79 | 0.27 | ug/m3 |
| 156-59-2 | 96.94 | cis-1,2-Dichloroethylene | ND | 0.20 | 0.077 | ppbv | | ND | 0.79 | 0.31 | ug/m3 |
| 10061-01-5 | 111 | cis-1,3-Dichloropropene | ND | 0.20 | 0.062 | ppbv | | ND | 0.91 | 0.28 | ug/m3 |
| 541-73-1 | 147 | m-Dichlorobenzene | ND | 0.20 | 0.040 | ppbv | | ND | 1.2 | 0.24 | ug/m3 |
| 95-50-1 | 147 | o-Dichlorobenzene | ND | 0.20 | 0.15 | ppbv | | ND | 1.2 | 0.90 | ug/m3 |
| 106-46-7 | 147 | p-Dichlorobenzene | ND | 0.20 | 0.038 | ppbv | | ND | 1.2 | 0.23 | ug/m3 |
| 10061-02-6 | 111 | trans-1,3-Dichloropropene | ND | 0.20 | 0.10 | ppbv | | ND | 0.91 | 0.45 | ug/m3 |

ND = Not detected MDL = Method Detection Limit

RL = Reporting Limit

E = Indicates value exceeds calibration range

J = Indicates an estimated value

B = Indicates analyte found in associated method blank

N = Indicates presumptive evidence of a compound

Report of Analysis

| | | | |
|-------------------|---|-----------------|----------|
| Client Sample ID: | CAMS 630 | Date Sampled: | 12/25/21 |
| Lab Sample ID: | JD37553-1 | Date Received: | 12/31/21 |
| Matrix: | AIR - Ambient Air Comp. Summa ID: A1174 | Percent Solids: | n/a |
| Method: | TO-15 | | |
| Project: | Valero-CAMS, Baton Rouge, LA | | |

VOA TO15 List

| CAS No. | MW | Compound | Result | RL | MDL | Units | Q | Result | RL | MDL | Units |
|-----------|--------|---------------------------|--------|-------|-------|-------|---|--------|------|-------|-------|
| 64-17-5 | 46.07 | Ethanol | 2.8 | 0.50 | 0.39 | ppbv | | 5.3 | 0.94 | 0.73 | ug/m3 |
| 100-41-4 | 106.2 | Ethylbenzene | 0.16 | 0.20 | 0.061 | ppbv | J | 0.69 | 0.87 | 0.26 | ug/m3 |
| 141-78-6 | 88 | Ethyl Acetate | ND | 0.20 | 0.10 | ppbv | | ND | 0.72 | 0.36 | ug/m3 |
| 622-96-8 | 120.19 | 4-Ethyltoluene | ND | 0.20 | 0.095 | ppbv | | ND | 0.98 | 0.47 | ug/m3 |
| 76-13-1 | 187.4 | Freon 113 | ND | 0.20 | 0.031 | ppbv | | ND | 1.5 | 0.24 | ug/m3 |
| 76-14-2 | 170.9 | Freon 114 | ND | 0.20 | 0.050 | ppbv | | ND | 1.4 | 0.35 | ug/m3 |
| 142-82-5 | 100.2 | Heptane | 0.28 | 0.20 | 0.092 | ppbv | | 1.1 | 0.82 | 0.38 | ug/m3 |
| 87-68-3 | 260.8 | Hexachlorobutadiene | ND | 0.20 | 0.062 | ppbv | | ND | 2.1 | 0.66 | ug/m3 |
| 110-54-3 | 86.18 | Hexane | 0.84 | 0.20 | 0.11 | ppbv | | 3.0 | 0.70 | 0.39 | ug/m3 |
| 591-78-6 | 100 | 2-Hexanone | ND | 0.20 | 0.15 | ppbv | | ND | 0.82 | 0.61 | ug/m3 |
| 67-63-0 | 60.1 | Isopropyl Alcohol | 0.87 | 0.20 | 0.19 | ppbv | | 2.1 | 0.49 | 0.47 | ug/m3 |
| 75-09-2 | 84.94 | Methylene chloride | 0.20 | 0.20 | 0.056 | ppbv | | 0.69 | 0.69 | 0.19 | ug/m3 |
| 78-93-3 | 72.11 | Methyl ethyl ketone | 0.19 | 0.20 | 0.11 | ppbv | J | 0.56 | 0.59 | 0.32 | ug/m3 |
| 108-10-1 | 100.2 | Methyl Isobutyl Ketone | ND | 0.20 | 0.073 | ppbv | | ND | 0.82 | 0.30 | ug/m3 |
| 1634-04-4 | 88.15 | Methyl Tert Butyl Ether | ND | 0.20 | 0.080 | ppbv | | ND | 0.72 | 0.29 | ug/m3 |
| 80-62-6 | 100.12 | Methylmethacrylate | ND | 0.20 | 0.070 | ppbv | | ND | 0.82 | 0.29 | ug/m3 |
| 115-07-1 | 42 | Propylene | 0.98 | 0.50 | 0.14 | ppbv | | 1.7 | 0.86 | 0.24 | ug/m3 |
| 100-42-5 | 104.1 | Styrene | ND | 0.20 | 0.12 | ppbv | | ND | 0.85 | 0.51 | ug/m3 |
| 71-55-6 | 133.4 | 1,1,1-Trichloroethane | ND | 0.20 | 0.037 | ppbv | | ND | 1.1 | 0.20 | ug/m3 |
| 79-34-5 | 167.85 | 1,1,2,2-Tetrachloroethane | ND | 0.20 | 0.048 | ppbv | | ND | 1.4 | 0.33 | ug/m3 |
| 79-00-5 | 133.4 | 1,1,2-Trichloroethane | ND | 0.20 | 0.038 | ppbv | | ND | 1.1 | 0.21 | ug/m3 |
| 120-82-1 | 181.5 | 1,2,4-Trichlorobenzene | ND | 0.20 | 0.12 | ppbv | | ND | 1.5 | 0.89 | ug/m3 |
| 95-63-6 | 120.19 | 1,2,4-Trimethylbenzene | 0.18 | 0.20 | 0.087 | ppbv | J | 0.88 | 0.98 | 0.43 | ug/m3 |
| 108-67-8 | 120.19 | 1,3,5-Trimethylbenzene | ND | 0.20 | 0.080 | ppbv | | ND | 0.98 | 0.39 | ug/m3 |
| 540-84-1 | 114.2 | 2,2,4-Trimethylpentane | 0.37 | 0.20 | 0.095 | ppbv | | 1.7 | 0.93 | 0.44 | ug/m3 |
| 75-65-0 | 74.12 | Tertiary Butyl Alcohol | ND | 0.20 | 0.093 | ppbv | | ND | 0.61 | 0.28 | ug/m3 |
| 127-18-4 | 165.8 | Tetrachloroethylene | ND | 0.040 | 0.014 | ppbv | | ND | 0.27 | 0.095 | ug/m3 |
| 109-99-9 | 72.11 | Tetrahydrofuran | ND | 0.20 | 0.090 | ppbv | | ND | 0.59 | 0.27 | ug/m3 |
| 108-88-3 | 92.14 | Toluene | 0.85 | 0.20 | 0.057 | ppbv | | 3.2 | 0.75 | 0.21 | ug/m3 |
| 79-01-6 | 131.4 | Trichloroethylene | ND | 0.040 | 0.019 | ppbv | | ND | 0.21 | 0.10 | ug/m3 |
| 75-69-4 | 137.4 | Trichlorofluoromethane | 0.22 | 0.20 | 0.036 | ppbv | | 1.2 | 1.1 | 0.20 | ug/m3 |
| 75-01-4 | 62.5 | Vinyl chloride | ND | 0.20 | 0.069 | ppbv | | ND | 0.51 | 0.18 | ug/m3 |
| 108-05-4 | 86 | Vinyl Acetate | ND | 0.20 | 0.11 | ppbv | | ND | 0.70 | 0.39 | ug/m3 |
| | 106.2 | m,p-Xylene | 0.59 | 0.20 | 0.14 | ppbv | | 2.6 | 0.87 | 0.61 | ug/m3 |
| 95-47-6 | 106.2 | o-Xylene | 0.21 | 0.20 | 0.077 | ppbv | | 0.91 | 0.87 | 0.33 | ug/m3 |
| 1330-20-7 | 106.2 | Xylenes (total) | 0.80 | 0.20 | 0.077 | ppbv | | 3.5 | 0.87 | 0.33 | ug/m3 |

| CAS No. | Surrogate Recoveries | Run# 1 | Run# 2 | Limits |
|----------|----------------------|--------|--------|---------|
| 460-00-4 | 4-Bromofluorobenzene | 97% | | 65-128% |

ND = Not detected

MDL = Method Detection Limit

J = Indicates an estimated value

RL = Reporting Limit

B = Indicates analyte found in associated method blank

E = Indicates value exceeds calibration range

N = Indicates presumptive evidence of a compound

Misc. Forms

Custody Documents and Other Forms

Includes the following where applicable:

- Chain of Custody
- Summa Canister and Flow Controller Log

AIR

CHAIN OF CUSTODY

SGS North America Inc. - Houston Air Sampling Field Data Sheet



10165 Harwin Dr, Ste 150 Houston, TX 77036
TEL: 713-271-4700 FAX: 713-271-4770
www.sgs.com/ehsusa

FEDEX Tracking # 77561818560
Lab Quote # SW-12621-135
Lab Job # JD37553

PAGE ___ OF ___

| Client / Reporting Information | | | | Project Information | | | | Weather Parameters | | | | Requested Analysis | | | | |
|--|--------------------------------|--|---------------------------------|--|--------------------------------|---|----------------------|-------------------------------|-------------------------|---|-----------------|----------------------|-------------------------------|-------------------------------------|------------------|--------------|
| Company Name <i>Providence Eng.</i> | | | | Project Name <i>Valero Refining</i> | | | | Temperature (Fahrenheit) | | | | | | | | |
| Address <i>1201 Main St.</i> | | | | Street | | | | Start | | Maximum: | | | | | | |
| City <i>Boston Rouge</i> | | | | State <i>LA</i> | | Zip <i>70802</i> | | Stop | | | | | | Minimum: | | |
| Project Contact <i>Brandon Kipatrik</i> | | | | City <i>Meranda</i> | | | | State <i>LA</i> | | | | | | Atmospheric Pressure (inches of Hg) | | |
| E-mail <i>brandenkipatrik@providenceeng.com</i> | | | | Project # <i>712-001</i> | | | | Start | | | | | | Maximum: | | |
| Phone # <i>225-766-7400</i> | | | | Client Purchase Order # | | | | Stop | | | | Minimum: | | | | |
| Sampler(s) Name(s) <i>Kenneth Paik / Chris Grant</i> | | | | Other weather comment: | | | | | | | | | | | | |
| Lab Sample # | Field ID / Point of Collection | Air Type | | | Start Sampling Information | | | | | Stop Sampling Information | | | | | | |
| | | Indoor(I) Soil Vapors(SV) / Ambient(A) Grab (G) | Canister Serial #/ Tedlar | Size 6L or 1L | Flow Controller Serial # | Date | Time (24hr clock) | Canister Pressure ("Hg) | Interior Temp (F) | Sampler Init. | Date | Time (24hr clock) | Canister Pressure ("Hg) | Interior Temp (F) | Sampler Init. | |
| <i>1</i> | <i>CAMS 630</i> | <i>A</i> | <i>A1174</i> | <i>6L</i> | <i>537</i> | <i>12/24/12</i> | <i>0945</i> | <i>30</i> | <i>63</i> | <i>KP</i> | <i>12/25/12</i> | <i>0945</i> | <i>5.5</i> | <i>62</i> | <i>CGX</i> | <i>Summa</i> |
| Turnaround Time | | Data Deliverable Information | | | | Comments / Remarks | | | | | | | | | | |
| Standard <input type="checkbox"/> 10 Business Days <input type="checkbox"/> 5 Business Days <input type="checkbox"/> 3 Business Days <input type="checkbox"/> 2 Business Days <input type="checkbox"/> 1 Business Day <input type="checkbox"/> Other | | Approved By: _____ Date: _____ | | | | All NJDEP TO-15 is mandatory Full T1 Comm A _____ Comm B _____ Reduced T2 _____ Full T1 _____ Other: _____ | | | | Initial Assessment <i>TJ US</i> Label Verification _____ | | | | | | |
| Sample Custody must be documented below each time samples change possession, including courier delivery. | | | | | | | | | | | | | | | | |
| Relinquished by: | Date / Time: | Received By: | Date / Time: | Relinquished By: | Date / Time: | Received By: | Date / Time: | Relinquished By: | Date / Time: | Received By: | Date / Time: | Relinquished By: | Date / Time: | Received By: | Date / Time: | |
| <i>1 Christopher Grant</i> | <i>12/25/12</i> | <i>FedEx</i> | <i>12/25/12</i> | <i>FedEx</i> | <i>12/25/12</i> | <i>FedEx</i> | <i>12/25/12</i> | <i>FedEx</i> | <i>12/25/12</i> | <i>FedEx</i> | <i>12/25/12</i> | <i>FedEx</i> | <i>12/25/12</i> | <i>FedEx</i> | <i>12/25/12</i> | |
| Relinquished by: | Date / Time: | Received By: | Date / Time: | Relinquished By: | Date / Time: | Received By: | Date / Time: | Relinquished By: | Date / Time: | Received By: | Date / Time: | Relinquished By: | Date / Time: | Received By: | Date / Time: | |
| <i>3</i> | | | | | | | | | | | | | | | | |
| Relinquished by: | Date / Time: | Received By: | Date / Time: | Relinquished By: | Date / Time: | Received By: | Date / Time: | Relinquished By: | Date / Time: | Received By: | Date / Time: | Relinquished By: | Date / Time: | Received By: | Date / Time: | |
| <i>5</i> | | | | | | | | | | | | | | | | |

White Original: SGS copy Color Copy: Client copy

Copy of EHSQA-QAC-0059-00-FORM-Houston - Air COC (5).xlsx
Rev. Date: 04/2010

JD37553: Chain of Custody

Page 1 of 2



31
3

SGS Sample Receipt Summary

Job Number: JD37553

Client: PROVIDENCE ENG

Project: PROVIDENCE - CAMS

Date / Time Received: 12/31/2021 10:00:00 AM

Delivery Method: _____

Airbill #'s: _____

Cooler Temps (Raw Measured) °C:

Cooler Temps (Corrected) °C:

Cooler Security

Y or N

Y or N

- | | | | | | |
|---------------------------|-------------------------------------|--------------------------|-----------------------|-------------------------------------|--------------------------|
| 1. Custody Seals Present: | <input checked="" type="checkbox"/> | <input type="checkbox"/> | 3. COC Present: | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| 2. Custody Seals Intact: | <input checked="" type="checkbox"/> | <input type="checkbox"/> | 4. Smpl Dates/Time OK | <input checked="" type="checkbox"/> | <input type="checkbox"/> |

Cooler Temperature

Y or N

- | | | |
|------------------------------|--------------------------|--------------------------|
| 1. Temp criteria achieved: | <input type="checkbox"/> | <input type="checkbox"/> |
| 2. Cooler temp verification: | N/A | |
| 3. Cooler media: | N/A | |
| 4. No. Coolers: | N/A | |

Quality Control Preservation

Y or N

N/A

- | | | | |
|---------------------------------|-------------------------------------|--------------------------|-------------------------------------|
| 1. Trip Blank present / cooler: | <input type="checkbox"/> | <input type="checkbox"/> | <input checked="" type="checkbox"/> |
| 2. Trip Blank listed on COC: | <input type="checkbox"/> | <input type="checkbox"/> | <input checked="" type="checkbox"/> |
| 3. Samples preserved properly: | <input checked="" type="checkbox"/> | <input type="checkbox"/> | |
| 4. VOCs headspace free: | <input type="checkbox"/> | <input type="checkbox"/> | <input checked="" type="checkbox"/> |

Sample Integrity - Documentation

Y or N

- | | | |
|--|-------------------------------------|--------------------------|
| 1. Sample labels present on bottles: | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| 2. Container labeling complete: | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| 3. Sample container label / COC agree: | <input checked="" type="checkbox"/> | <input type="checkbox"/> |

Sample Integrity - Condition

Y or N

- | | | |
|----------------------------------|-------------------------------------|--------------------------|
| 1. Sample recvd within HT: | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| 2. All containers accounted for: | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| 3. Condition of sample: | Intact | |

Sample Integrity - Instructions

Y or N N/A

- | | | | |
|---|-------------------------------------|-------------------------------------|-------------------------------------|
| 1. Analysis requested is clear: | <input checked="" type="checkbox"/> | <input type="checkbox"/> | |
| 2. Bottles received for unspecified tests | <input type="checkbox"/> | <input checked="" type="checkbox"/> | |
| 3. Sufficient volume recvd for analysis: | <input checked="" type="checkbox"/> | <input type="checkbox"/> | |
| 4. Compositing instructions clear: | <input type="checkbox"/> | <input type="checkbox"/> | <input checked="" type="checkbox"/> |
| 5. Filtering instructions clear: | <input type="checkbox"/> | <input type="checkbox"/> | <input checked="" type="checkbox"/> |

Test Strip Lot #s: pH 1-12: 231619 pH 12+: 203117A Other: (Specify) _____

Comments

SM089-03
Rev. Date 12/7/17

JD37553: Chain of Custody

Page 2 of 2

Summa Canister and Flow Controller Log

Job Number: JD37553
Account: PROVLABR Providence Engineering
Project: Valero-CAMS, Baton Rouge, LA
Received: 12/31/21

32
3

| SUMMA CANISTERS | | | | | | | | | | | | | |
|-----------------|-------|-----------|----------|----|-----------|------------|---------------|----------|-----|----------|-----------|------------|----------|
| Shipping | | | | | | | Receiving | | | | | | |
| Summa ID | Vac L | Date " Hg | Date Out | By | SCC Batch | SCC FileID | Sample Number | Date In | By | Vac " Hg | Pres psig | Final psig | Dil Fact |
| A1174 | 6 | 29.4 | 12/06/21 | SG | CP11444 | 5W46550.D | JD37553-1 | 01/05/22 | DFT | 5.5 | | | 1 |

SGS Bottle Order(s):
 SW-12621-135

Prep Date **Room Temp(F)** **Bar Pres "Hg**
 12/06/21 70 29.92